

MODELS LC26SD1EK LC32SD1EK LC37SD1EK LC42SD1EK

SYMPTOM Bottom part of analogue teletext graphics missing.

CAUSE Software issues for IC3002 VCT.

ACTION Update the software for IC3002 to latest versions.



These images show the “Bottom half analogue teletext, missing” phenomenon.

Sharp Electronics (UK) Limited

Reference – SP072004x

Revision - 1

White – Carry out as required

Yellow – Carry out as required and whenever the unit comes in for service

Red – Carry out on all units